

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER  
AECOM'S ASH POND VISUAL SITE INSPECTION REPORT - 2020**

**Documented to meet 257.83(b)(5)**

	<b>DEFICIENCY/OBSERVATION (inspection recommendation #)</b>	<b>CORRECTIVE MEASURE</b>
1	Minor potholing was observed at the edge of the riprap channel on the southern extent of the embankment.	Added riprap to affected areas.