

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S ASH POND VISUAL SITE INSPECTION REPORT - 2022**

Documented to meet 257.83(b)(5)

DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
	Three erosion rivulets upslope from the northern toe of the buttress slope.
Area was regraded along with adding drain to eliminate future issues, then seeded and strawed to re-establish vegetation.	